

GLOBAL EARTHQUAKE MODEL 2018 A Step Toward Earthquake Resilience

5th of December 2018 | 0900h - 1800h | CAR College, Pavia, Italy




## IMPACTS AND LESSONS FROM THE RECENT INDONESIAN EARTHQUAKE IN LOMBOK AND PALU 2018



M. Asrurifak<sup>\*)</sup>, Masyhur Irsyam, Lutfi Faisal, Danny Hilman, Sri Widiantoro Irwan Meilano, Wahyu Triyoso, & Sri Hidayati

<sup>\*)</sup> Pusat Studi Gempa Nasional (PuSGeN) - National Research Center for Earthquake Team for Updating of Sesimic Hazard Maps of Indonesia 2010 and 2017 Lecturer ISTN Jakarta



### On behalf of:

Pusat Studi Gempa Nasional (PuSGeN) National Research Center for Earthquake






### Acknowledgement:



#### Earthquake events since the release of building code SNI 1726-2002




Wes

# DEADLY EARTHQUAKES IN 2018

Ekonografik Dkatadata

Indonesia kembali berduka. Gempa bumi dan tsunami melanda Sulawesi Tengah. Sepanjang 2018 telah terjadi banyak gempa dengan magnitudo di atas 5, dan menelan korban.




# infografis GEMPA BUMI NTB

infographic EARTHQUAKE WEST NUSA TENGGARA

### LAPORAN SITUASI 33

Situation Report of 33

Minggu, 2 September 2018 Sunday, 2 September 2018



### infographics SITUATION REPORT

# EARTHQUAKE & TSUNAMI DONGGALA-PALU-SIGI CENTRAL SULAWESI





Disater: EARTHQUAKE & TSUNAMI Location : CENTRAL SULAWESI FRIDAY, 28 sept 2018 5 PM

UPDATE Friday, 30 Nopember 2018

## DATA VICTIM & DAMAGED





#### familylinks.icrc.org/indonesia

Data Website until 29 November 2018 I AM ALIVE = 54 I AM LOOKING FOR = 1445 SATPHONE = 2 CLOSE = 223 HANDPHONE = 58 RED CROSS MESSAGE (RCM) = 7


# Tribute to Lombok & Palu:

Our thoughts and prayers are with victims, families, and whoever impacted by Lombok & Palu Earthquake.

We wish the community for a quickly complete recovery.

# **OUTLINE:**

- Tectonic Condition of Indonesia
- Indonesian Seismic Hazard Map
- Active Faults & Earthquakes in Lombok & Palu
- Impacts & Lessons from The Recent Earthquake in Lombok & Palu 2018
- Closing




### Major Tectonics around Indonesia (Bock et al., 2003)


- There are 4 major tectonic plates in this region: Eurasia, Indoaustralia, Pacific and Philipine.
- Indoaustralia and Philipine/pacific plates subduct beneath the Eursia plate with the rate of 6cm/year and 12 cm/year

Stories about earthquakes in Indonesia as a realization of the dynamics of Plate Tectonic (Referring The Work Of Robert Hall)

# Indonesia is one of the most seismically active countries in the world, it is epicenter all shock situation Indonesia tectonic regime.




# Shallow Earthquake 1900-2016



# **OUTLINE:**

- Tectonic Condition of Indonesia
- Indonesian Seismic Hazard Map
- Active Faults & Earthquakes in Lombok & Palu
- Impacts & Lessons From The Recent Earthquake In Lombok & Palu 2018
- Closing



The National Hazard Maps Have been Implemented in Earthquake Resistance Building and Infrastructure Design Codes in Indonesia

Buildings Return period of earthquake 2,500 yrs and 1% risk of collapse in 50 yrs



Bridges Return period of earthquake 1,000 yrs





Metro Tunnels 1,000 yrs



Dams: 2,500-10,000 yrs






Railway Bridges: 500-1000 yrs



Offshore Platforms: 500 - 2,500 yrs

**Port and Airport** 


Ss Risk-Adjusted Maximum Considered Earthquake (MCE<sub>R</sub>) Ground Motion Parameter for Indonesia for 0.2-s Spectral Response Acceleration (5% of Critical Damping), Site Class BC



Using USGS & OpenQuake Software for Analysis

asrurifak@gmail.com


Ss Risk-Adjusted Maximum Considered Earthquake (MCE<sub>R</sub>) Ground Motion Parameter for Indonesia for 1.0-s Spectral Response Acceleration (5% of Critical Damping), Site Class BC



Using USGS & OpenQuake Software for Analysis

asrurifak@gmail.com

#### Maximum Considered Earthquake Geometric mean (MCE<sub>G</sub>) PGA



Using USGS & OpenQuake Software for Analysis

asrurifak@gmail.com

#### Efforts to Enhance the 2017 National Seismic Hazard Maps



niștry of Ministry of I

Ministry of Energy+ Mineral Resources National Disaste

Ministry of Public Works














- Enhancement is conducted by updating earthquake sources data including geology, seismology, geodesy, and earthquake catalog.
- Updating data is based upon the latest studies such as recent active-fault studies utilizing trenching, carbon dating, epicenter relocation, strain analysis from GPS data, availability of basic data including the SRTM-30, IFSAR, LiDAr, and earthquake catalog up to 2016.
- Improvement of tomography using 3D velocity model.
- Adding several active faults that were not quantified before.
- Considering the latest GMPE published after Tohoku earthquake and latest NGA.
- Adding OpenQuake software for comparison and verification to USGS and EZFRisk software.

# **OUTLINE:**

- Tectonic Condition of Indonesia
- Indonesian Seismic Hazard Map
- Active Faults & Earthquakes in Lombok & Palu
- Impacts & Lessons From The Recent Earthquake In Lombok & Palu 2018
- Closing


### LATEST INFORMATION ON SEISMIC SOURCES PARAMETERS THAT HAVE NOT BEEN ACCOMMODED IN OLD HAZARD MAP (2010)




Input Parameters Indonesian hazard map, 2010

### **NEW PARAMETER FOR SEISMIC SOURCES 2017**


#### (251 ACTIVE FAULT FOR INPUT PSHA)




SUMATRA ACTIVE FAULT AND SURROUNDING




JAVA ACTIVE FAULT AND SURROUNDING




SULAWESI ACTIVE FAULT AND SURROUNDING



#### NUSATENGGARA-BANDA ACTIVE FAULT AND SURROUNDING




**NEW PARAMETER FOR SEISMIC SOURCES 2017** 




**KALIMANTAN ACTIVE FAULT AND SURROUNDING** 

### **MEGATHRUST PARAMETERS FOR INPUT PSHA 2017**




## EQ EPICENTER FROM PUSGEN CATALOG (1900-2016)



### EQ EPICENTER FROM PUSGEN CATALOG

11000 2010



# **OUTLINE:**

- Tectonic Condition of Indonesia
- Indonesian Seismic Hazard Map
- Active Faults & Earthquakes in Lombok & Palu
- Impacts & Lessons From The Recent Earthquake In Lombok & Palu 2018
- Closing

## Impact Lombok Eq. 2018



### Buildings Collapse Lombok Eq. 2018



### "STRONG COLUMN WEAK BEAM" CONSEPT NOT YET APPLIED








### **MINIMUM STANDARD OF REINFORCEMENT**








## LANDSLIDE Lombok Eq. 2018






## LIQUIFACTION & GROUND CRACKING Lombok Eq. 2018



### LESSONS LEARNED FROM LOMBOK EARTHQUAKE


#### Lombok Earthquake Intensity Map in MMI by BMKG



PERCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme
POTENTIAL	none	none	none	Very light	Light	Moderate	Mod./Heavy	Heavy	Very Heavy
PEAK ACC.(%g)	<0.05	0.3	2.8	6.2	12	22	40	75	>139
PEAK VEL.(cm/s)	<0.02	0.1	1.4	4.7	9.6	20	41	86	>178
INSTRUMENTAL	1	11-111	IV	V	VI	VII	VIII	18	<b>X</b> +

M6.4, 29 Juli 2018






INSTRUMENTAL	1	11-111	IV	V	VI	VII	VIII	IX	X+
PEAK VEL.(cm/s)	<0.02	0.1	1.4	4.7	9.6	20	41	86	>178
PEAK ACC.(%g)	< 0.05	0.3	2.8	6.2	12	22	40	75	>139
POTENTIAL DAMAGE	none	none	none	Very light	Light	Moderate	Mod/Heavy	Heavy	Very Heavy
PE RCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme

M7.0, 5 Agustus 2018



BMKG ShakeMap : Lombok Timur - NTB AGS 19, 2018 21:56:27 WIB, M:6.9, 8.44LS 116.68BT, KedImn:10km.




INSTRUMENTAL INTENSITY	1	11-111	IV	V	VI	VII	VIII	IX	X+
PEAK VEL.(cm/s)	<0.02	0.1	1.4	4.7	9.6	20	41	86	>178
PEAK ACC.(%g)	< 0.05	0.3	2.8	6.2	12	22	40	75	>139
DAMAGE	none	none	none	Very light	Light	Moderate	Mod./Heavy	Heavy	Very Heavy
PE RCEIVED SHAKING	Not felt	Weak	Light	Moderate	Strong	Very strong	Severe	Violent	Extreme

#### M6.9, 19 Agustus 2018


#### Value of MMI about VII



#### Design and Recorded Response Spectra at Geophysics Taliwang Station M 7.0 Lombok Earthquake 2018



#### Maximum Considered Earthquake Geometric mean (MCE<sub>G</sub>) PGA in Building Code SNI-1726-2012



## LESSONS LEARNED EATHQUKAE IMPACT TO BUILDING CASE STUDY: LOMBOK Eq. 2018

VII MMI scale → converted to PGA about 0.18-0.34g (Actual G Motion)


Indonesian Risk Map (MCE<sub>G</sub>) SNI 1726:2012 for Lombok  $\rightarrow$  0.4-0.5g (bedrock)


on surface, Peak Surface Acceleration (PSA)  $\rightarrow$  the value will be multiply with amplification factor depend on site class condition

In fact  $\rightarrow$  many buildings that have structural damage (from medium to heavy), even to collapse due to the earthquake that occurred

**→** Buildings not designed in accordance with seismic design standards

### **LESSONS LEARNED FROM PALU EARTHQUAKE**







- PGA & MMI
  EW: 281gal VII, NS: 203gal VII, UD: 335gal VI
  - Horizontal vector: 333gal VIII
  - 3 component vector: 400gal VIII

(Sigit Pramono, 2018)

#### PGA Vs Distance with M = 7.4




#### Maximum Considered Earthquake Geometric mean (MCE<sub>G</sub>) PGA in Building Code SNI-1726-2012





**Design and Recorded Response Spectra at Geophysics Station of Palu** 



Same case with Lombok Eq

PALU EQ → Actual GM < Design GM → but, many buildings collapse

#### **LESSONS LEARNED FROM PALU/DONGGALA EARTHQUAKE**



## BUILDINGS COLLAPSE Palu Eq. 2018



## BUILDINGS COLLAPSE Palu Eq. 2018



## DAMAGE & LIQUIFACTION Palu Eq. 2018





Hotel Roa Roa di kawasan Maesa di Kelurahan Lolu Timur, Kota Palu, luluh lantak dihantam rangkaian gempa yang melanda Sulawesi Tengah. Puluhan tamu belum diketahui nasibnya. (KOMPAS.com/ROSYID A ATLAN)

Tim SAR menemukan salah satu korban meninggal dunia dari reruntuhan Hotel Roa Roa Palu akibat gempa, Minggu (30/9/2018). (Dok Humas Kantor SAR Palu)

## **BRIDGE COLLAPSE**




















Wood and car transported by Tsunami





Mosque in front of the Gas Station

**Yellow Bridge** 


## **Ground Cracking**

#### Ground Cracking at Palu Airport

## Ground Cracking, Jono oge village

# Lokasi SPBU Sigi

## Soil Condition, Liquefaction, and Landslide




EGENDA


Ratas Adv



Euri, Delorme, NPS, Ortile Layer Service

Peta Rupa Burni Indonesia, BIG lebaran Puskesmas Kementerian Kesehatan Sebaran Pengungsi Crowdsourcing SMA Madani Pala dan PUSPICS USM Deliniasi Likultaksi berdasarkan Citra Digitalglobe 01 Oktober 2018





## Jono oge village (Youtube, 2018)



## 1197523015 119154/201E 119°54'30°E 110/04/4015 119°55'30°E Jono oge village

11015411019

#### ANALISIS :

Arah dan akumulasi aliran didapatkan dari hasil analisis data DEMNAS dan Foto Udara menggunakan analisis hidrologi spasial. Pergerakan aliran mengarah dari timur laut menuju ke Sungai Langaleso di bagian selatan dan seterusnya menuju Sungai Salu Miu di bagian barat wilayah likuifaksi. Aliran air ini terakumulasi di 2 tempat, yakni Desa Langaleso dan Desa Kobobona.


1101521001

1101522010

119157-007

## **Direction of Flow Liquefaction**





PETA ANALISIS ARAH DAN AKUMULASI ALIRAN WILAYAH LIKUIFAKSI - DESA SIDERA JONO OGE KECAMATAN SIGI BIROMARU, KABUPATEN SIGI

UPDATE PETA : 12 Oktober 2018

Proyeksi Lintang-Bubur Unit Datum WG5 - 1984

119"SENTE

- Gambar Dasar : Exrl, Delorme, NPS, Ortile Layer Service Batas Administrasi : 8P5 2013
- umber data
- Sumber Data I. 1. Foto Udara, BNPB dan PUPR . 2. Citra Satetit Digital Globe Tanggal 1 Oktober 2018. 3. Demma, Badan Informati Geospania (1953). 3. Analitis and altiran, Peoperas Gempa Sultang. 4. Analitiss akumulasi altran, Peoperas Gempa Sultang.

119154/501

110155101

110154/2018

119'55-60'E

- BNPB BADAN INFORMASI PUSDATINMAS PUPR GEOSPASIAL Diolah & Diinformasikan Oleh :
- POS PENDAMPING NASIONAL (POSPENAS) Kantor Gubernur Provinsi Sulawesi Tengah Ji. DR. Sam Ratulangi, Bersusu, Palu Timur, Kota Palu Email: gempasulteng.bnpb@gmail.com Call Center Pospenas: (0451) 8203019


## **Soil Condition & Liquefaction**



# Petobo village (Youtube, 2018)

## **Flow Liquefaction Failure**

## Petobo village (Youtube, 2018)



#### ANALISIS :


KALDKURHL.

CI SELATAN

Arah dan akumulasi aliran didapatkan dari hasil analisis data DEMNAS dan Foto Udara menggunakan analisis hidrologi spasial. Pergerakan aliran mengarah dari timur menuju Anak Sungai Palu yang berada di bagian barat wilayah likuifaksi dan selanjutnya menuju ke Sungai Palu. Saat hujan, aliran ini akan terakumulasi ke Desa Mpanau bagian utara, Desa Petobo bagian barat, dan Desa Kalukubula bagian utara.

11975472018

## **Direction of Flow Liquefaction**



11015414078


















#### Toe of failure







(e) Rotational and/or Translational Sliding

## Petebo village




		ರ		-		20 40 60 80
2	5.55	-			Medium dense brown gravelly SAND	
	0.00				Medium dense brown fine SAND	
	10.00				Medium dense grey SAND	
12	12.00				Dense grey gravelly SAND	- + + + - + - + -               - + - + - + -





## SIBALAYA VILLAGE



KEMENTERIAN PEKERJAAN UMUM DAN PERUMAHAN RAKYAT BADAN PENELITIAN DAN PENGEMBANGAN JALAN DAN JEMBATAN JIAH. Nasution No. 264 PO BOX 2 Bandung 40294 Indonesia Telp. (022) 7802251 Fax (022) 7802726 email: Info@pusjatan.pu.go.id










## Houses have moved approximately 400m

## LAND SUBSIDENCE



## CLOSING

- We are still mourning the victims of the earthquake in Lombok and Palu, hoping that people will recover quickly.
- **Recorded PGA at Lombok range 180-340 gal & Palu range from 200-350 gal.**
- Impact of Palu Eq: ground cracking, tsunami, landslide, liquefaction, and ground shaking are a huge natural disaster event and will be a future learning
  This is a huge laboratory for natural disasters
- Palu Eq: the rupture offset was found as large as 4-6 meters horizontal sinistral offset and about half meter vertical offset.
- > Liquefaction has resulted in extreme flow liquefaction and lateral spreading.
- Material losses and injuries or death are usually not caused by earthquakes directly, but because buildings or infrastructure are designed not to follow seismic design building standards (Earthquake doesn't kill)
- Stakeholders in the construction sector must seriously pay attention to the rules of building seismic resistance based on the current code provisions.

## Thank you for the continuous support from:



Public Works





Ministry of Energy+ Mineral Resources



Ministry of Transportation



National Disaster Management Authority Bureau of Meteorology,



Climatology,

Geophysics



Indonesia Research Institute

Agency



Australian Government

**Geoscience** Australia





To:



